Ultrasonic Sensors with Solid State Relay Output

P-1256-1 819-0456

Technical Data Sheet





Ultrasonic Sensors

with Isolated Solid State Relay Outputs

fitted with Range and Hysteresis Control





Sensing range Switching functions/output		1011016 mm (4-40") 2 Solid State Relays	2032032 mm (8-80") 2 Solid State Relays
Electrical data Voltage range min./max. Input current Transducer frequency Short circuit protected LED Response time Range control		20-30V DC reverse polarity protected 50mA 212 KHz Yes Yes - green (not detecting), red (detecting) 30 mSec Range and Hysteresis	20-30V DC reverse polarity protected 50mA 150 KHz Yes Yes - green (not detecting), red (detecting) 50 mSec Range and Hysteresis
Mechanical data Temperature range min./max. Degree of protection Body material Termination cable 2 m/6 ft. Plug/socket		0°C/+60°C / 32°F/140°F IP 65/NEMA 12 Valox plastic PVC 4 x 22 gauge Versions available to order	0°C/+60°C / 32°F/140°F IP 65/NEMA 12 Valox plastic PVC 4 x 22 gauge Versions available to order

104 mm

4.1'

1) Brackets for M 30 x 1.5

Accessories

Humidity

Ordering Information

Plastic - BK5-D34PA Part number 596-0223-041

Metal - M 30 ST

Part number 7430-448-003


1) Brackets 0-95% non-condensing

Dimensions


30mm 1.18" Adjustment Pots
Detection and Hysteresis
Control

1) Brackets

0-95% non-condensing



Wiring Data




Output Specification


- 2 x Solid state relays N.O. / N. C.
- 160V AC or V DC 100mA continuous
- Short circuit protected
- 1500 volts RMS isolation

Ultrasonic Sensors

Operation and Set-Up



Beam Spread vs. Target Distance



Proximity Sensing

Proximity detection is the detection of an object at a set distance. The sensing range is controlled by the "Range Control" potentiometer. Any object within the desired range is detected while objects beyond the set range are ignored. The sensing distance is dependent upon the sensor chosen, 40" or 80".


In the proximity mode of operation, the hysteresis potentiometer must be turned to 'off' by turning the pot counterclockwise.

Hysteresis Control


The sensor is also fitted with a hysteresis control potentiometer. This control allows you to adjust the turn off point while the detection potentiometer sets the "turn on" point.

(Example: Range pot set for 10", hysteresis pot set for 20". With these settings the sensor will detect when the target reaches 10" and stays on as the target moves away to 20".) This hysteresis can be adjusted from .5" to 40" from the detect point with the 40" sensor and 1" to 80" with the 80" sensor.

Proximity Sensing



Hysteresis Control



Sensors, Industrial Switches and Safety Technology Products

Warner Electric has many years of experience in applying sensors in motion control applications. Warner Electric's broad range of innovative and technologically advanced product range offers our customers the exact solution to satisfy their sensing applications.

Our full product range is available through more than 800 distributor locations, throughout the United States. Canada and Mexico.

Local Sales Support is provided by a well trained sales force that is backed up by Application Engineering providing immediate technical support.





Non-Contact Sensors

Photoelectric Sensors Ultrasonic Sensors Inductive Proximity Sensors Capacitive Sensors Magnetic Sensors

Industrial Switches

Limit Switches Foot Switches Cable Pull Switches

Safety Technology Products

Safety Interlocks Cable Pull Switches Coded Magnetic Monitoring Systems



Approvals and Certification

Each model is individually identified with its own certification. Documentation is available upon request.



Warner Electric LLC 449 Gardner Street • South Beloit, IL 61080 815-389-3771 • Fax: 815-389-2582 www.warnerelectric.com

P-1256 819-0456 7/05 Printed in USA